K

Suzanne Steab - July 2010 Inspection Report

From:

Karl Houskeeper

To:

krus8416@aol.com

Date:

7/29/2010 1:23 PM

Subject:

July 2010 Inspection Report

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: Bear Canyon July 2010.pdf

Attached is the July 2010 inspection report for Bear Canyon.

Thanks,

Karl



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:

OGM Karl Houskeeper

Inspection Report

Permit Number:	C0150025
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, July 14, 2010
Start Date/Time:	7/14/2010 8:00:00 AM
End Date/Time:	7/14/2010 1:00:00 PM
Last Inspection:	Tuesday, June 29, 2010

Inspector: <u>Karl Houskeeper</u>,
Weather: <u>Clear, Temp. 76 Deg. F.</u>
InspectionID Report Number: <u>2423</u>

Accepted by: jhelfric 7/29/2010

Permitee: HIAWATHA COAL CO INC
Operator: HIAWATHA COAL CO INC
Site: BEAR CANYON MINE

Address: ,

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

10,991.83	Total Permitted			
40.46	Total Disturbed			
	Phase I			
	Phase II			
	Phase III			

Mineral Ownership

✓ Federal

ral

☐ State ☐ County

✓ Fee☐ Other

Types of Operations

Underground

☐ Surface ☐ Loadout

☐ Processing ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Kenny Defa Price Mine Service (PMS) was present for the inspection.

Inspector's Signature:

Karl Houskeeper,

Inspector ID Number: 49

Date

Wednesday, Ju

ay, Ju**DNR**10

OIL, GAS & MININ

Inspection Type: PARTIAL

Inspection Date: Wednesday, July 14, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Frankris a	Nat Americant	0	F.6
1.	Permits, Change, Transfer, Renewal, Sale	Evaluated	Not Applicable	Comment	Enforcemen
2.	Signs and Markers	<u> </u>		<u> </u>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures			<u> </u>	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
 5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste		П		
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.			П		
11.	Contemporaneous Reclamation			-	
12.					
13.	Revegetation				_ <u></u>
14.	Subsidence Control				
15.	Cessation of Operations				
	Roads: Construction, Maintenance, Surfacing	П			
	Roads: Drainage Controls				
	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	<u> </u>		<u> </u>	$\overline{\Box}$
	AVS Check			<u>_</u> _	
20.	Air Quality Permit				
	Bonding and Insurance				$\overline{\Box}$
22.	Other				

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Wednesday, July 14, 2010

Page 3 of 3

2. Signs and Markers

The mine identification sign is at the point of public access to the permit area.

4.c Hydrologic Balance: Other Sediment Control Measures

The bridge crossing into the Office/Bath House area has been repaired. Silt fence was laid against the logs and then covered with dirt to provide an effective berm to protect the stream buffer zone.

18. Support Facilities, Utility Installations

A piece of metal sheeting has come loose from the main belt line and is on the ground. The sheeting needs to be removed from the ground and either replaced on the belt line or disposed of.